

COMPLETION REPORT

1	Name of the work	Providing and Supplying of water tankers in Bagalur Division Dasarahalli Division.		
2	Sanctioned Estimate No. & Date	Pono. 20100/76/3		
3	Head of Account which is chargeable	1001 17 H		
4	Instrument Order NO. & Date	Wono: 20100/113/13-1404 30-6-20		
5	Name Of Contractor	K. R. D. D.		
6	Time Stipulated for Completion of work			
a				
b	Delay in Exculation of Work			
7	Measurement recorded in	M.B.M. 2402 p.m. 340229		
8	Check Measurement of the Asst			
9	Name of the office/official in charge of the work			
10	a) Asst. Eng/junior Eng	D. S. S. S. S.		
	b) Asst. Exe Engineer	S. S. S. S.		
Sanctioned Estimate Amout		Amout Claims As per Actually Vide As per bills	Excess	Savings
S.W		49904900	—	95700

- 1) Certified that the above work has been completed within the stipulated time noted in the
- 2) Certified that the contractor has delayed and completed the work for which necessary fine recovered
- 3) Certified that the above work has been executed by the contractor satisfactory in


ASSISTANT ENGINEER


ASSISTANT EXECUTIVE ENGINEER

ಇ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಖ್ಯಾತ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಖಾಸಗಿ, ಬೆಂಗಳೂರು - 560 073